
ADANGER



HAZARDOUS ATMOSPHERE

Vent silo and chute thoroughly before entering.

ADANGER



HAZARDOUS ATMOSPHERE

Use self-contained breathing apparatus or ventilation adequately before entry.

AWARNING



SPONTANEOUS COMBUSTION HAZARD

Keep silage above 40% moisture.

Cap unused silos and empty abandoned silos.

AWARNING



SLIP/FALL HAZARD

Be physically able to climb and use a ladder.

Do not climb if you are using medications or alcohol.